DEPARTMENT OF ENVIRONMENT, HEALTH AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Vanderbilt West APPLICANT: 4BR 8/31/17
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9/5/17
PROPOSED FACILITY: 4BR MH comm PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

1126 533

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	7% Linear	0-8	scl wsbk	FV ss sp sep	Grayish Red				PS .3
		8-17	cl sbk	FV/F ss sp sef					
		17-48	c sbk	F sp sef	Red				
2	8% Linear	0-9	scl wsbk	FV ss sp sef					PS .3
		9-18	cl sbk	FV/F ss sp sef					
		18-48	c sbk	F s sp sef					
3	7% Linear Repair	0-16	cl sbk	F ss sp					2R .20
		16-40	c sbk	F ss sp					
		40-48	cl sbk	F ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Gravity 25%	Gravity 50%
Site LTAR	.3	.20

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: [signature]
OTHER(S) PRESENT: _____