DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #: 4705-97-4906
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Hayden Investments / Village Point #7 APPLICATION DATE 11/22/11
ADDRESS: 183 Village Point Dr DATE EVALUATED:
PROPOSED FACILITY: 3bR House PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: 0.57ac
LOCATION OF SITE: 183 Village Point Drive PROPERTY RECORDED:
WATER SUPPLY: • Private • Public • Well • Spring • Other
EVALUATION METHOD: • Auger Boring • Pit • Cut TYPE OF WASTEWATER: • Sewage • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 6%	0-7	gr / L	vfr / sop	NA	48"	NA	NA	PS 0.3
		7-20	ssk / scl	fr / sop					
		20-39	ssk / c	fi / sop					
		39-48	ssk / cl	fr / sop					
2	L 7%	0-11	gr / sl	vfr / sop	NA	48	NA	NA	PS 0.3
		11-22	ssk / scl	fr / sop					
		22-40	ssk / c	fi / sop					
		40-48	wssk / cl	fr / sop					
3	L 7%	0-9	gr / L	vfr / sop	NA	48	NA	NA	PS 0.3
		9-20	ssk / cl	fr / sop					
		20-39	ssk / c	fi / sop					
		39-48	wssk / cl	fr / sop					
4	L 6%	0-7	gr / L	vfr / sop	NA	48	NA	NA	PS 0.3
		7-21	ssk / cl	fr / sop					
		21-38	ssk / c	fi / sop					
		38-48	wssk / cl	fr / sop					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	III
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TCH
OTHER(S) PRESENT:

COMMENTS: