DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: [redacted] Munday APPLICANT: ___
ADDRESS: 152 Patricia Rd Statesville APPLICATION DATE: 1-25-2000 DATE EVALUATED: 1-25-2000
PROPOSED FACILITY: 2 Bdrm House PROPOSED DESIGN FLOW (.1949): 240 PROPERTY SIZE: 3.11 Ac
LOCATION OF SITE: Lot 19 Rushmore Hills Hwy 64 W (L) Cal. Ey Pass (R) Cherry Blossom PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other 4th Lot on Right
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 3.5%	0-12	SAB C	FR SH/FP					PS .3
		12-36	SAB C SH/MA	FR VFR					
		36-52	SAB C SH/MA	FR					
2	L 5.8%	0-24	SAB C SH/MA	FR					PS .3
		24-52	SAB C SH/MA	FR VFR					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	Y	Y
System Type(s)	Conventional	Same
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [redacted]
OTHER(S) PRESENT: Septic