Johnny Dant

12667.

IREDELL COUNTY HEALTH DEPARTMENT

39685

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR GANT BLDG. COMPANY DATE 7-23-91 PERMIT NO. 91-1-A-(1-3)

PHONE: Business _____ Home _____

LOCATION Hwy 90W past Scotts School-T.L. on Lackey Farm Rd. - 2nd house on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. 1, 2 & 3. SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 3.5

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Prev. Suitable.
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	1 gal./sq. ft.
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Level
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10 ft
			Rock or other impervious formations	none observed.

Lot Area Ample.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250. Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 120 Linear Ft. 400
Depth of Stone in Lines 12

Water Supply: Individual ( )
Public (✓)

Installed by Foothills Plumbing Co.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 7-25-91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold