10807.

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR DANNY MAYBERRY DATE 12-7-89 PERMIT NO. 95-2-B-29.

PHONE: Business _____ Home _____

LOCATION Hwy 90W-T.L. on Lackey Farm Rd. just past Scotts School go approx. one mi. T.L. on dirt rd. Blue mailbox on rt. keep to left on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1.5

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 20,000 sq. ft.

Character & Porosity of Soil Fair Suitable


Percolation Rate 60 Min/in

Topography 2-5% Slope

Depth to Water Table 70+ ft.

Rock or other impervious formations None

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 225 Linear Ft. 240
Depth of Stone in Lines 12 in.

Water Supply: Individual ( )
Public (✓)

Installed by Charles Connelly

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

Plot of System

IMPROVEMENTS PERMIT BY Steve Barnes

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Barnes DATE 12-7-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold