DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #: 4706435950
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rovira's Construction — APPLICATION DATE 2-9-11
ADDRESS: 135 Ridge Run — DATE EVALUATED: 3-10-11
PROPOSED FACILITY: 3BR — PROPOSED DESIGN FLOW (.1949): 360 — PROPERTY SIZE: 633
LOCATION OF SITE: 135 Ridge Run — PROPERTY RECORDED: n/a
WATER SUPPLY: ☒ Private • Public • Well • Spring • Other
EVALUATION METHOD: ☒ Auger Boring • Pit • Cut — TYPE OF WASTEWATER: ☒ Sewage • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10% LS	0-6	CL SBK	SS SP	n/a	48	n/a	n/a	.25 PS
		6-48	C SBK	SS SP					
2	10% LS	0-8	CL SBK	SS SP	n/a	48	n/a	n/a	.25 PS
		8-48	C SBK	SS SP					
3	10% LS	0-6	CL SBK	SS SP	Chr. 4 42"	48	n/a	n/a	.25 PS
		6-48	C SBK	SS SP					
4	10% LS	0-11	CL SBK	SS SP	Chr. 4 43"	48	n/a	n/a	.25 PS
		11-48	C SBK	SS SP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	III
Site LTAR	.25	.25

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: James Stewart
OTHER(S) PRESENT: None

COMMENTS:

LEGEND

use the following standard abbreviations

LANDSCAPE POSITION	GROUP	SOIL TEXTURE	CONVENTIONAL .1955 LTAR*	LPP .1957 LTAR*	MINERALOGY/ CONSISTENCE	STRUCTURE
CC (Concave Slope)	I	S (Sand)	1.2 - 0.8	0.6 - 0.4	NEXP (Non-expansive)	G (Single Grain)
CV (Convex Slope)		LS (Loamy Sand)			SEXP (Slightly Expansive)	M (Massive)
D (Drainage Way)					EXP (Expansive)	CR (Crumb)
DS (Debris Slump)	II	SL (Sandy Loam)	0.8 - 0.6	0.4 - 0.3		GR (Granular)
FP (Flood Plain)		L (Loam)				SBK (Subangular Blocky)
FS (Foot Slope)						ABK (Angular Blocky)
H (Head Slope)	III	Si (Silt)	0.6 - 0.3	0.3 - 0.15		PL (Platy)
L (Linear Slope)		SiCL (Silty Clay Loam)				PR (Prismatic)
N (Nose Slope)		CL (Clay Loam)			**MOIST**	**WET**
R (Ridge)		SCL (Sandy Clay Loam)			VFR (Very Friable)	NS (Non-sticky)
S (Shoulder Slope)		SiL (Silt Loam)			FR (Friable)	SS (Slightly Sticky)
T (Terrace)					FI (Firm)	S (Sticky)
	IV	SC (Sandy Clay)	0.4 - 0.1	0.2 - 0.05	VFI (Very Firm v. Very Sticky)	VS (Very Sticky)
		SiC (Silty Clay)			EFI (Extremely Firm)	NP (Non-plastic)
		C (Clay)				SP (Slightly Plastic)
		O (Organic)	None	None		P (Plastic)
						VP (Very Plastic)

*Adjust LTAR due to depth, consistence, structure, soil wetness, landscape, position, wastewater flow and quality.


NOTES

HORIZON DEPTH	In inches below natural soil surface
DEPTH OF FILL	In inches from land surface
RESTRICTIVE HORIZON	Thickness and depth from land surface
SAPROLITE	S(suitable) or U(unsuitable)
SOIL WETNESS	Inches from land surface to free water or inches from land surface to soil colors with chroma 2 or less - record Munsell color chip designation
CLASSIFICATION	S (Suitable), PS (Provisionally Suitable), or U (Unsuitable)

Evaluation of saprolite shall be by pits.

Long-term Acceptance Rate (LTAR): gal/day/ft^2

Show profile locations and other site features (dimensions, reference or benchmark, and North).



DENR (######)
Review (#####)