IREDELL COUNTY HEALTH DEPARTMENT

STATESVILLE 704-878-5305 CI MOORESVILLE 704-664-5281

IMPROVEMENT PERMIT / AUTHORIZATION TO CONSTRUCT / OPERATION PERMIT / EXISTING SYSTEM INSPECTION

PERMIT# 120530 PIN# 4711-46-7065 LEB DATE 11-9-04

OWNER OR CONTRACTOR GLADYS + JOHN DEBOSK PHONE: Business CLAYTON HOMES 704-682-3218 Home [redacted] 321-255-2153

ADDRESS 2460 LAVEMENT RD MELBOURNE, FL 32934

LOCATION BUFFALO SHOALS WEST (E) LONGBOAT DR (CORNER OF LONGBEACH & PELOS

SUBDIVISION BUFFALO SHOALS BLOCK / SECTION ____ LOT 48 LOT AREA 1.0 AC SITE CLASS PS DESIGN FLOW 240 L.T.A.R. .12

Septic Tank: 1000 Gallons; STB 1000 Date 6-23-04
Pump Tank: 1000 Gallons; PT 17 Date 5-22-04
Pump Make: Wedsull Model 600405 Serial No. S2054637786
Nitrification Field: No Fields 1 Square Feet 2000' Linear Feet 400'
No Lines 8 Trench Width 18" Max Trench Bottom Depth 12" Gravel Depth 8"

☒ New System ☐ Repair System Type: I, II, III, IV, V, VI
System Description: Low Pressure Pipe
Repair System Description: MAX FEASIBLE/NO REPAIR NEEDED
Maintenance Agreement Required: ☒ Yes ☐ No

☐ House/Mod. Home ☒ Mobile Home ☐ Business ☐ Other
No. Bedrooms 2 No. Bathrooms 2 No. Employees ____

☐ Slab ☒ Crawl Space ☐ Basement w/plumbing ☐ Basement wo/plumbing

Water Supply: ☐ Individual ☒ Public ☒ Community

Comments/Conditions: (1) USE IN LINE PUMP FILTER IN PUMP TANK (2) DO NOT CUT FOR POSITIVE DRAINAGE. MUST BE BACKFILLED TO MEET THE REQMTS (3) NOTE 6" MINIMUM BACKFILL REQMT OF P.S. SOIL

INITIAL SITE SKETCH

SEE ATTACHED PLANS FOR SYSTEM DESIGN BY ASHLY ROLLINS, LSS

Comments/Conditions: (4) MAINTAIN SETBACKS (5) LOT WAS DEEDED BY JULY 1, 1977, SEPTIC PORTION LINES CAN BE 5' FROM P/L (6) LOT WAS DEEDED B4 JANUARY 1, 1983 SO REPAIR AREA IS NOT REQUIRED (7) ATTACHED DEED FOR LOT 48 IS DATED

AS BUILT SKETCH AUGUST 6, 1970

RABBIT FILTER & METER 11-18-04
LINES & PRESSURE 11-19-04
NEEDS ELECTRICIAN/MAN/ 46" BACKFILL
+ CONTRACT
EVERYTHING ELSE OK
NEEDS BREAKER BOX LABELED/ 3 CIRCUITS
BRKRS LABELED. EVERYTHING OK

Permit can be suspended or revoked if any false information is supplied toward securing the permit/any unauthorized changes are made to the site/any unauthorized changes are made in the installation of the system. Improvement Permit with plat valid without expiration. Improvement Permit with site plan valid for sixty months. Authorization to Construct is valid for a period equal to that of Improvement Permit – not to exceed sixty months.

Signed: _____ date 11-9-04 Installed by: A-1 BACKHOE

Improvement Permit by: _____ date 11-9-04 Operation Permit by: _____ date 12-2-04

Authorization to Construct by: _____ date 11-9-04 Existing System Inspection by: _____ date _____

HEALTH DEPT. COPY: WHITE OWNER COPY (FINAL): YELLOW OWNER COPY (INITIAL): PINK