HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY I.D.#: _____
PROPERTY RECORDED: _____
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Sunwood builders OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 1-13-95
PROPOSED FACILITY: 3 bed
PROPERTY SIZE:
LOCATION OF SITE: Woodland Acres #33 section
WATER SUPPLY: On-Site Well X Comm. Well Public Other EVAL. METHOD: Auger Boring Pit X Cut

PROFILE #	.1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	
1	LS 10%	0-5"	gr	gr	fr	.1942 WETNES CONDITION -
		5-26/27"	C	sbk/pbk	fi	.1943/.1956 SAPROLITE - 37"
		26/27-37/40" Tr	C	pbk/M	fi	.1944 RESTRICTIVE HORIZON -
		37/40"+ mostly rock				.1948 PROFILE CLASSIFICATION -
		water seeping downslope @			37"	PROFILE LTAR -
2	LS	0-5"	gr	gr	fr	.1942 WETNES CONDITION -
		5-8"	cl	sbk	fi	.1943/.1956 SAPROLITE - 37"
		8-30/48"	C	sbk/pbk	fi	.1944 RESTRICTIVE HORIZON -
		30/31-37/40" Tr	C	sbk/M	fi	.1948 PROFILE CLASSIFICATION -
		>37/40" mostly rock				PROFILE LTAR -
3	LS	0-3/4"	gr	gr	fr	.1942 WETNESS CONDITION -
		3/4-9/10	scl	sbk	fi	.1943/.1956 SAPROLITE -
		9/10-35	C	sbk/pbk	fi	.1944 RESTRICTIVE HORIZON -
		35-45" Tr	C	sbk/M	fi	.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
4	LS 10%	0-4"	gr	gr	fr	.1942 WETNESS CONDITION -
		4-28/39"	C	sbk	fi	.1943/.1956 SAPROLITE -
		28/39-42"	C	sbk(w)	fi	.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
5						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3
OTHER FACTORS(.1946) SYSTEM TYPE Conventional 18" deep
EVALUATED BY: Joe Flynn OTHER(S) PRESENT:
COMMENTS: interceptor drain - upper property line 36-48" deep - install when dry if unsaved sake sidewalls

DRAFT

0001956