SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Sunwood OWNER AGENT PHONE:
ADDRESS: APPLICATION DATE DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: lot 39 Woodland
WATER SUPPLY: On-Site Well Comm. Well Public SOIL SERIES EVAL. METHOD: Auger Boring Pit

PROFILE #	1980 LANDSCAPE POSITION	HORIZON DEPTH (IN.)	1971 STRUCTURE/PORE	1941 MORPHOLOGY/ CONSISTENCE	1943 WETNESS COND.	1944 RESTRICT HORIZONS	1958 CLASS OF HORIZ	1951/ 1956 SAPRIST CLASS.	HO L
1	Linear 10%	0 to 48	C SBK		chroma 3 at 36"	PS	PS	PS	3
2	Linear 12%	0 to 48	C SBK		PS	PS	PS	PS	3
3									
4									
5									

AVAILABLE SPACE (1980): SITE CLASSIFICATION (1980): LONG TERM ACCEPTANCE RATE: 3
EVALUATED BY: OTHERS PRESENT:
COMMENTS: