DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Malcolm Barnes APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-10-97
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 3 bdrm PROPERTY SIZE: _____
LOCATION OF SITE: Lot 41 Mahaley Village PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut Removed old trees
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L 25%	0-6	sl b brn	fr					PS .34
		6-32	sab sc/cl	fr-fr					
		32-48	wksab brwn	fr fr					
2	L 25%	0-8	sab sc/l	fr					
		8-48	wksab sbk sc/l	l sap fr ss sp	wp				
			usable sap within 36"						
3		0-21	sab sc/l	fr sp					
		21-31	wksab brwn sc/l	brwn l sap fr ss sp					
		31-48	gr sab gr-brwn sl sap	fr ss wp					
			usable sap within 36"						
4		0-20	sab sc/cl	fr sp					PS .13 @ 42"
		20-42	wksab brn sc/cl	w sap fr ss sp					
		42-48	gr sab brn, brn l sap						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

PS .5 0-6 gr sab sc/cl fr / 6-24 sab sc/cl fr sp ss wp / 24-48" wksab brwn sc/cl fr sp ss wp .13

00030018