DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET ____ OF ____

PROPERTY I.D.#: ____

DATE: ____

COUNTY: ____

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: Bob Compton

ADDRESS: ____

OWNER ___ AGENT: ___ PHONE: ____

APPLICATION DATE: ____ DATE EVALUATED ____

PROPOSED FACILITY: ____

PROPERTY SIZE: ____

LOCATION OF SITE: Lot 2 Garden PK Happy Lun

WATER SUPPLY: On-site Well ___ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ___ Pit ___ Cut ___

PROFILE #	1940 LANDSCP POS./ SLOPE(%)	HOR ZON DEPTH (IN)	1941 (a)(1) TEXTURE	(a)(2) STRUCTURE	(a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	linear 4 6%	0+6	L	GR				.1942 Wetness Cond. - N/A
		6+24	C	SBK	1:1			.1943 Depth/.1956 Sapr. - 36"
		24+36	B/C					.1944 Restrictive Hori. - Rock 36+48
		36+48	Clay Saprolite weather Rock					.1948 Profile Class. - PS to 36"
								Profile LTAR - .3
2	linear 10%	0+5	L	GR				.1942 Wetness Cond. - N/A
		5+16	C	SBK	1:1			.1943 Depth/.1956 Sapr. - 36"
		16+36	B/C					.1944 Restrictive Hori. - ROCK
		36+48	Saprolite weathered Rock					.1948 Profile Class. - PS to 36
								Profile LTAR - .3
3	linear 10%	0+6	L	GR				.1942 Wetness Cond. - N/A
		6+24	C	SBK	1:1			.1943 Depth/.1956 Sapr. - 36"
		24+36	CL	weak SBK	1:1			.1944 Restrictive Hori. - Rock
		36+ Rock						.1948 Profile Class. - PS
								Profile LTAR - .35
4								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -

AVAILABLE SPACE (.1945) yes OTHER FACTORS (.1946) ____ SITE CLASSIFICATION (.1948) PS

SYSTEM TYPE ____ LONG-TERM ACCEPTANCE RATE(S) .35

EVALUATED BY: J. C. Moore OTHER(S) PRESENT: County Worsen Mike Dennis

COMMENTS: ____

0029811