00801

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR AUSTIN HUNT LUMBER CO. DATE 10-14-83 PERMIT NO. _____

PHONE: Business _____ Home _____


LOCATION 64-70 west on (R) at corner of Faye-Gilbert Rd.

SUBDIVISION NAME _____ LOT NO. _____ S. R. No. _____

House ( ) Mobile Home ( ) Business (✓) Other Shelter over equipment - no plumbing or water under pressure. SECTION OR BLOCK NO. _____

No. Bedrooms _____ No. Bathrooms none

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil _____
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate _____
Auto. Wash. Machine	Yes ( )	No (✓)	Topography _____
Site Suitable	Yes (✓)	No ( )	Depth to Water Table _____
Lot Area Ample			Rock or other impervious formations _____



Plot of System

Size of Tank _____ Gals.

Nitrification Field:

No. of Lines _____

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual ( )

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: No septic tank system at this site. This is a lumber storage yard.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE 10-14-83

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold