IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION 2:30 pm.
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR DAN Wiles DATE 3/14/85 PERMIT NO.

PHONE: Business Home

LOCATION Enter Ashbrook Pk. off 64-70 West, left at forks, 5th house on right


SUBDIVISION NAME Ashbrook Park LOT NO. S. R. No. SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate
Auto. Wash. Machine	Yes (✓)	No ( )	Topography Repair
Site Suitable	Yes (✓)	No ( )	Depth to Water Table
Lot Area Ample			Rock or other impervious formations

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank Existing Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 360 Linear Ft. 120
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public (✓)

Installed by Wes Lytton

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: old lines left intact, upper line to feed first, new tee set ✓

CERTIFICATE OF COMPLETION BY Charles D. Sindlen, R.S. DATE 3/14/85

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold