IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tarlton Rinaldo DATE 5/22/75 PERMIT NO.

PHONE: Business Home

LOCATION 90W., T.L. into Coral Lagoon Acres (Tarlton Rd), TR on John Todd Ave, TL on Carlyn St., last house on left S. R. No.

SUBDIVISION NAME LOT NO. 11 SECTION OR BLOCK NO.


House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 132 X 168 approx

Character & Porosity of Soil Red Clay
Percolation Rate appx
Topography Slope to Front
Depth to Water Table unknown
Rock or other impervious formations none observed



Plot of System

Size of Tank 1,000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)

Installed by Cline & Gilleland

IMPROVEMENTS PERMIT BY

COMMENTS: Due to stub out of home, system was changed to the front of the lot.

CERTIFICATE OF COMPLETION BY Andrew E. Causey DATE 5/22/75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold