IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Carlton-Rinaldo Sita Lumber Co. DATE 6-23-75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy # 90 above Loray Tab. int. Carol Lynn acres, 3rd House on L. S. R. No. _____

SUBDIVISION NAME Carol-Lynn Acres LOT NO. 48 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 41,600 sq ft

Character & Porosity of Soil Red Clay
Percolation Rate Sub. Division Acc
Topography Slope to rear & Lot Low
Depth to Water Table _____
Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 936 Linear Ft. 312
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)

Installed by Cline-Gilleland

IMPROVEMENTS PERMIT BY William M. Howard

COMMENTS: Divert Downspouts & Surface Water away from Tank & Lines

CERTIFICATE OF COMPLETION BY E. G. Gluteson DATE 6-23-75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold