DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY RECORDED: _____
COUNTY: Iredell

# SOIL/SITE EVALUATION
## FOR
## ON-SITE WASTEWATER SYSTEM

APPLICANT: Nancy Lineberger OWNER/AGENT: _____ PHONE: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-23-94
PROPOSED FACILITY: 3 Bedroom DW MH
PROPERTY SIZE: _____
LOCATION OF SITE: Lot # 31 Westridge S/D
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

| PROFILE # | 1941 LANDSCP POS SLOPE % | HORIZON DEPTH (IN.) | 1941 (a)(2) TEXTURE | 1941 (a)(2) STRUCTURE | 1941 (a)(2) MINERALOGY | |
|---|---|---|---|---|---|---|
| 1 | 6-8% L | 0-25" | Fill material | | | 1942 WETNESS CONDITION - — |
| | | | | | | 1943/1956 SAPROLITE - NA |
| | | | | | | 1944 RESTRICTIVE HORIZON - over 2' of fill material |
| | | | | | | 1945 PROFILE CLASSIFICATION - U. |
| | | | | | | PROFILE LTAR - — |
| 2 | 6-8% L | 0-31" | Fill material | | | 1942 WETNESS CONDITION - — |
| | | | | | | 1943/1956 SAPROLITE - NA |
| | | | | | | 1944 RESTRICTIVE HORIZON - over 2' of fill material |
| | | | | | | 1945 PROFILE CLASSIFICATION - U. |
| | | | | | | PROFILE LTAR - — |
| 3 | 3-5% L | 0-3" | l | gr | 1:1 / vfr | 1942 WETNESS CONDITION - P.S |
| | | 3"-44" | c | sbk | 1:1 / fr | 1943/1956 SAPROLITE - 44"-↑ |
| | | 44"-↑ | Saprolite | | | 1944 RESTRICTIVE HORIZON - NA |
| | | | | | | 1945 PROFILE CLASSIFICATION - P.S |
| | | | | | | PROFILE LTAR - .35 |
| 4 | 4-6% L | 0-4" | l | gr | 1:1 / vfr | 1942 WETNESS CONDITION - P.S. |
| | | 4"-48" | c | sbk | 1:1 / fr | 1943/1956 SAPROLITE - NA |
| | | | | | | 1944 RESTRICTIVE HORIZON - NA |
| | | | | | | 1945 PROFILE CLASSIFICATION - P.S |
| | | | | | | PROFILE LTAR - .35 |
| 5 | 4-6% L | 0-5" | l | gr | 1:1 / vFr | 1942 WETNESS CONDITION - P.S. |
| | | 5"-48" | c | sbk | 1:1 / Fr | 1943/1956 SAPROLITE - NA |
| | | | | | | 1944 RESTRICTIVE HORIZON - NA |
| | | | | | | 1945 PROFILE CLASSIFICATION - P.S. |
| | | | | | | PROFILE LTAR - .35 |

AVAILABLE SPACE (1945): P.S. SITE CLASSIFICATION (1945): P.S. SITE LONG TERM ACCEPTANCE RATE: .35 gpd/ft²
OTHER FACTORS (1945): _____ SYSTEM TYPE: Pump to conventional
EVALUATED BY: Michael G. Dennis OTHER(S) PRESENT: Nancy Lineberger
COMMENTS: 100% Repair Pump to ppaps

DRAFT

0139 8