13435.

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR VAN & SHERRY GRANT DATE 10-7-91. PERMIT NO. 91-10-A-15.

PHONE: Business _____ Home _____

LOCATION Hwy 90W - T.R. on Little Farm Rd. - T.L. on Peacock Holler - 2nd house on left. S. R. No. _____

SUBDIVISION NAME CONCORDIA PLACE. LOT NO. 15. SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Replacement of one drain line that is to be abandoned.

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil _____

Percolation Rate _____


Topography EXISTING SEPTIC

Depth to Water Table _____

Rock or other impervious formation TANK SYSTEM.

Lot Area Ample.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank EXISTING. Gals.

Nitrification Field:

No. of Lines 4

Sq. Ft. 240 Linear Ft. 80

Depth of Stone in Lines 12

Water Supply: Individual ( )

Public ✓

Installed by Mike Holland

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Hedrick

COMMENTS: Inside drain line abandoned because of addition.

CERTIFICATE OF COMPLETION BY Steve Brown DATE 10-7-91.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold