DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Johnny Morrison / Morrison Fields #1
ADDRESS: _____
PROPOSED FACILITY: 3 BR Home
PROPOSED DESIGN FLOW (.1949): 360 gpd
LOCATION OF SITE: Scuffle Creek. Tr Entrance is on Colson Loop
APPLICATION DATE _____
DATE EVALUATED: _____
PROPERTY SIZE: 6.44 acres
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 7%	0-6	cr / SL	vfr / sap	>18	>18	-	-	PS 0.7
		6-18+	sbk / c	fi / sap					
2	L 7%	0-7	cr / L	vfr / sap	>18	>18	-	-	PS 0.7
		7-18+	sbk / c	fi / sap					
3	L 9%	0-8	cr / L	vfr / sap	>18	>18	-	-	PS 0.7
		8-18	sbk / c	fi / sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Trench 25%	Trench 50%
Site LTAR	0.7	0.7

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [illegible]
OTHER(S) PRESENT: _____

COMMENTS: _____