DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Johnny Morrison / Morrison Estates Lot #3 _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 22 Sept. 05
PROPOSED FACILITY: 3 bedroom PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: 0.411 Ac +/-
LOCATION OF SITE: South Creek TR Fortune Rd. ~1/4 mi. on Rt PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 0%	0-8	cr / sl	vfr / sap	>18	>18	-	-	PS 0.3
		8-18+	sbk / C	fi / sap					
2	L 6%	0-6	cr / sl	1-1 sap	>18	>18	-	-	PS 0.3
		6-48?	sbk / C	fi / sap					
3	L 6%	0-8	cr / sl	vfr / sap	>18	>18	-	-	PS 0.3
		8-48?	sbk / C	fi / sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III 25%	III 50%
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Ted
OTHER(S) PRESENT: _____

COMMENTS: 4 bedroom back / house location to be removed.