IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

REPAIR
OWNER OR CONTRACTOR HAROLD McKINNEY DATE 1/14/91 PERMIT NO. REPAIR

PHONE: Business _____ Home _____

LOCATION NC 90 W, TR LITRE FARM RD, TL 2ND JO MONNI ENTRANCE ON (L) AT END BEFORE LEFT TURN. S. R. No. _____

SUBDIVISION NAME JO MONNI AC. LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil PS
Percolation Rate .4 GPA / FT2
Topography 2-4 % LS
Depth to Water Table > 4'
Rock or other impervious formations SCATTERED ROCK

Lot Area AMPLE


(✓) Basement with Plumbing ____ Basement without Plumbing ____ No Basement

ACP 11/30/90

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 855 Linear Ft. 285
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)



Plot of System

Installed by TOMMY FRYE

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY STEVE HEDRICK

COMMENTS: _____

CERTIFICATE OF COMPLETION BY STEVE HEDRICK DATE 1/14/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold