IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Thad Stickleather DATE Aug 8, 1977 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 90N T.R. ON S.R. 1548 .8mi. on Rt.

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 4 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area _____

Character & Porosity of Soil Cecil clay loam
Percolation Rate —
Topography 2%
Depth to Water Table sink
Rock or other impervious formations none observed



Plot of System

Size of Tank existing Gals.
Nitrification Field:
No. of Lines 1
Sq. Ft. 300 Linear Ft. 100
Depth of Stone in Lines 10" +
Water Supply: Individual ( )
Public ( )

Installed by Jim Lackey

IMPROVEMENTS PERMIT BY Andrew E. Causey

COMMENTS: Repair

CERTIFICATE OF COMPLETION BY David R. Hinson DATE Aug 8, 1977

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold