HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY RECORDED: 9PA-9B (APT)
COUNTY: IREDELL

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: JOHN & RITA BARRINGER OWNER/AGENT: PHONE: 592-4865
ADDRESS: PO Box 147 APPLICATION DATE: 10/26/99 DATE EVALUATED: 10/26/99
UNION GROVE, NC 28689 PROPOSED FACILITY: 3BR MH
PROPERTY SIZE: 1.91 ACRES
LOCATION OF SITE: NC 115 N, TL MIDWAY RD, TR COVE GAP, TL 2ND DRIVEWAY
WATER SUPPLY: On-Site Well ✓ Comm Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	1941 (a)(1) TEXTURE	(a)(2) STRUCTURE	(a)(3) MINERALOGY	
1	L 8%	0-20	C	SBK	1:1 / FI/P	1942 WETNESS CONDITION: S
		20-48	C	SBK	1:1 / FR	1943/1956 SAPROLITE: S
						1944 RESTRICTIVE HORIZON: S
						1945 PROFILE CLASSIFICATION: PS
						PROFILE LTAR: 0.35 GPD/FT²
2						1942 WETNESS CONDITION: -
						1943/1956 SAPROLITE: -
						1944 RESTRICTIVE HORIZON: -
						1945 PROFILE CLASSIFICATION: -
						PROFILE LTAR: -
3						1942 WETNESS CONDITION: -
						1943/1956 SAPROLITE: -
						1944 RESTRICTIVE HORIZON: -
						1945 PROFILE CLASSIFICATION: -
						PROFILE LTAR: -
4						1942 WETNESS CONDITION: -
						1943/1956 SAPROLITE: -
						1944 RESTRICTIVE HORIZON: -
						1945 PROFILE CLASSIFICATION: -
						PROFILE LTAR: -
5						1942 WETNESS CONDITION: -
						1943/1956 SAPROLITE: -
						1944 RESTRICTIVE HORIZON: -
						1945 PROFILE CLASSIFICATION: -
						PROFILE LTAR: -

AVAILABLE SPACE (.1945): S SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: 0.35 GPD/FT²
OTHER FACTORS (.1946): NONE SYSTEM TYPE: CONV. GRAVITY
EVALUATED BY: S. HEDRICK OTHER(S) PRESENT: JOHN & RITA BARRINGER
COMMENTS:

DRAFT