DEPARTMENT OF ENVIRONMENT, [illegible]
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: 4717 74 6684
COUNTY: IREDELL

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bobby GRUBB
APPLICANT: SAME
ADDRESS: HUNTERSVILLE
APPLICATION DATE: 10-21-99
DATE EVALUATED: 11-8-99
PROPOSED FACILITY: 3BR House
PROPOSED DESIGN FLOW (.1949): 360
PROPERTY SIZE: 1.05 ACRES
LOCATION OF SITE: MTN. VIEW EST #26
PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	4% L	0-48	SBK / C	FR / NEXP					PS 0.3
2	LINEAR 4%	0-48	SBK / C	FR / NEXP					PS 0.3
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	II	III
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): NONE
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: J. HENDRICK
OTHER(S) PRESENT: BOBBY GRUBB