DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ONSITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION *for* ON-SITE WASTEWATER SYSTEM

OWNER: Saint Josephs Baptist Church
ADDRESS: ____ APPLICATION DATE ____
PROPOSED FACILITY: Church & Fellowship Hall PROPOSED DESIGN FLOW (.1949): ____ DATE EVALUATED: ____
LOCATION OF SITE: ____ PROPERTY SIZE: 3.8 Ac
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other ____ PROPERTY RECORDED: ____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L/SWPT HS 5%	0-9	gr L	vfr sap		7.18	—	—	PS 0.3
		9-18+	sbk C	fr-fi sap					
2	L 5%	0-8	gr L	vfr sap	7.48	7.18	—	—	PS 0.3
		8-18+	sbk C	fr-fi sap					
3	L 5%	0-9	gr L	vfr sap	7.48	7.18	—	—	PS 0.3
		9-18+	sbk C	fr sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	
System Type(s)	II	
Site LTAR	0.3	

COMMENTS: ____

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: JCH
OTHER(S) PRESENT: ____