DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Trinity Fore Dept. - Substation
ADDRESS: _____
PROPOSED FACILITY: Fire Dept. PROPOSED DESIGN FLOW (.1949): _____
LOCATION OF SITE: Pisgah ch. rd. from US 64 on Common Dishmore Lane

APPLICATION DATE _____
DATE EVALUATED: _____
PROPERTY SIZE: 2 Ac. more
PROPERTY RECORDED: _____

WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 5%	0-11	wssbk scl	vfr ssnp?	>18	>18	-	-	PS 0.3
		11-18+	sbk c	fi ssnp?					
2	L 7%	0-12	wssbk scl	vfr ssnp?	>18	>18	-	-	PS 0.3
		12-18+	ssbk c	fr-fi ssnp?					
3	L 7%	0-11	wssbk scl	vfr ssnp?	>18	>18	-	-	PS 0.3
		11-35	ssbk c	fi ssnp?					
		35-48+	wssbk c ssnp?	fr ssnp?					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____