4720 51 6774

SUBSURFACE WASTEWATER DISPOSAL SYSTEM MONITORING REPORT FORM

Date of Inspection [redacted] 6/24/07 __6 Mo. __12 Mo. __Follow-up __Service Call

Gary Baker
184 maple view Dr.
Troutman NC. 28166

County: Iredell — System Classification & Type: LP Panel III

Location of System

Lot # 101 Phase 2
Subdivision Wildlife Bay

(=Satisfactory, M=Marginal, X=Unsatisfactory, N=Not Evaluated, NA=Not Applicable)

TANKAGE (septic tanks)

			Scum Level	Sludge Level
Tank risers accessible?				
Signs of infiltration?		Septic Tank		
Tanks and access structurally sound?		Water Depth		
Sanitary tee(s) in good condition?		Septic Tank Needs Pumping		
Effluent filter cleaned?				
Effluent filter in good condition?				

EFFLUENT DOSING STATION

Tank riser height?		
Signs of infiltration?		
Required pumps present and operating properly?		
High water alarm operating properly?		
Floats, pipes, valves, disconnects in good condition?		
Control panel enclosure/components in good condition?		
Effluent appears clear and free of solids?		

GROUND ABSORPTION FIELDS (general)

No evidence of effluent surfacing?		
Surface water being effectively diverted away?		
Line cover & vegetative cover maintained properly?	X	Trim Bushes
Protected from traffic, destructive uses?		
Distribution devices in good working condition?	X	end cap to tight
Repair area properly reserved, maintained?		

LOW PRESSURE PIPE SYSTEM

Turnups/cleanouts/valves intact and accessible?	X
Laterals free of excess solids?	
Laterals flushed this inspection?	
Pressure head is properly adjusted?	

Pump Tank Size 1,000 gallons
Level Begin Dose 62 Level End Dose 67 Dose Amount (gallons) 100
Run Time 3 min Level Begin 62 Level End 67 Flow Amount 33 (gpm)

RECOMMENDATIONS TO OWNER: Last Line Cap could not be removed

COMPLIANCE STATUS: COMPLIANT ✓ NON-COMPLIANT ____

SIGNATURE OF "ORC" [signature]

SUBSURFACE WASTEWATER DISPOSAL SYSTEM MONITORING REPORT FORM

Date of Inspection 8-1-6-08

__6 Mo. ✓12 Mo.
✓Follow-up
__ Service Call

Gary Eaker
184 maple View Dr.
Troutman N.C. 28166

County: Iredell

System Classification & Type: LP Panel IV

Location of System

Lot # 101 Phase 2
Subdivision Wildlife Bay

(=Satisfactory, M=Marginal, X=Unsatisfactory, N=Not Evaluated, NA=Not Applicable)

TANKAGE (septic tanks)

			Scum Level	Sludge Level
Tank risers accessible?	✓			
Signs of infiltration?	✓	Septic Tank	____	____
Tanks and access structurally sound?	✓	Water Depth	____	
Sanitary tee(s) in good condition?	✓	Septic Tank Needs Pumping	____	
Effluent filter cleaned?	✓			
Effluent filter in good condition?	✓			

EFFLUENT DOSING STATION

Tank riser height?	✓	
Signs of infiltration?	✓	
Required pumps present and operating properly?	✓	
High water alarm operating properly?	✓	
Floats, pipes, valves, disconnects in good condition?	✓	
Control panel enclosure/components in good condition?	✓	
Effluent appears clear and free of solids?	✓	

GROUND ABSORPTION FIELDS (general)

No evidence of effluent surfacing?	✓	
Surface water being effectively diverted away?	✓	
Line cover & vegetative cover maintained properly?	X	Trim Bushes around end Caps.
Protected from traffic, destructive uses?	✓	
Distribution devices in good working condition?	X	Cap to tight.
Repair area properly reserved, maintained?	✓	

LOW PRESSURE PIPE SYSTEM

Turnups/cleanouts/valves intact and accessible?	✓
Laterals free of excess solids?	✓
Laterals flushed this inspection?	✓
Pressure head is properly adjusted?	✓

Pump Tank Size 1,000 gallons
Level Begin Dose 64 Level End Dose 70 Dose Amount (gallons) 120
Run Time 3 min Level Begin 64 Level End 70 Flow Amount 40 (gpm)

RECOMMENDATIONS TO OWNER: Last Line End Cap Cald not Be removed.

COMPLIANCE STATUS: COMPLIANT ✓ NON-COMPLIANT ____

SIGNATURE OF "ORC" [signature]