IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Dr. Benjamin E. Dunlap DATE 2/26/76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Trantham, T.R. on Old Mt. Rd, T.L. on E. Monbo Rd, go ½ mile and T.R. on dirt drive S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 4½

Garbage Disposal Unit	Yes	(✓)	No	( )	
Auto. Dishwasher	Yes	(✓)	No	( )	
Auto. Wash. Machine	Yes	(✓)	No	( )	
Site Suitable	Yes	(✓)	No	( )	

Lot Area 40 acres

Character & Porosity of Soil Sandy soil loam
Percolation Rate none
Topography on hillcrest
Depth to Water Table unk
Rock or other impervious formations none found



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Son Outlaw

IMPROVEMENTS PERMIT BY _____

COMMENTS: Washing Machine Drain = 1000 gal tank, 14 ton stone w/ tar paper cover, 10' of pipe

CERTIFICATE OF COMPLETION BY Andrew E. Causey DATE 3/1/76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold