DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Franklin

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: MARTHA Benfield APPLICANT: ___
ADDRESS: 118 Sycamore Ct Thornton APPLICATION DATE: 3.9.2000 DATE EVALUATED: 4.4.2000
PROPOSED FACILITY: 3 Bdrm PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 5 Ac
LOCATION OF SITE: Stubb Mill Rd (R) E. Monbo (L) Hicks Creek ½ mile on LFt gravel PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other Road before 224 Hicks Creek
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L-R 3-5%	0-16	G SL						PS.
		16-36	SAB^W C	FR SS SEEP					
		36-54	SAB^W C^H/SAP	FR					3
2	L S 8-10%	0-9	G SCL						PS
		9-30	SAB^W C	FR SS SEEP					
		30-48	C^H/SAP	FR					3
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	↘	↘
System Type(s)	Conventional	Future
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: C. Ellis
OTHER(S) PRESENT: Bart Holyfield