12637

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR ROGER POOLE DATE 6-28-91 PERMIT NO. 35-5-A-2

PHONE: Business _____ Home _____

LOCATION Compton Park Rd. off Old Mtn. Rd. - go appx. 3/4 mi. + T. R. on Maxwell Loop - go to end of cul-de-sac. S. R. No. _____

SUBDIVISION NAME COMPTON PARK. LOT NO. 23. SECTION OR BLOCK NO. _____

DOUBLEWIDE


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area Ample.

Character & Porosity of Soil Prov. Suitable.
Percolation Rate 4 min/in.
Topography Level
Depth to Water Table 18+
Rock or other impervious formations none observed.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by James Hubler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

The proposed GARAGE Addition addition does not appear to impact the existing septic system.

**NOTE: Attached garage - will be 53½ from well

R.S. _____

Date: 16 Dec 09

ICHD-Environmental Health Division

CERTIFICATE OF COMPLETION BY Steve Brown DATE 6-28-91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold