IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Edmiston Brickley DATE 10-11-75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Buffalo shoals Rd to Old Mt. Rd T.L. TR on 1535 House on L S. R. No. _____


SUBDIVISION NAME Compton Park LOT NO. 2 SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Coal Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Slope to Back
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	
			Rock or other impervious formations	

Lot Area 2.6 Acres



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 225 Linear Ft. 450
Depth of Stone in Lines 10
Water Supply: Individual (✓)
Public ( )

Installed by Hasty Lackey

IMPROVEMENTS PERMIT BY _____

COMMENTS: Well over 50' from Tank & Lines

CERTIFICATE OF COMPLETION BY J. David Eatmon DATE 10-15-75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold