DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICANT: Heritage Bldg Co
ADDRESS: 120 Hickory Point Dr Statesville APPLICATION DATE: 9 28 99 DATE EVALUATED: 10 22 99
PROPOSED FACILITY: 3 Bdrm House PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: .68
LOCATION OF SITE: Sold into Rd (2) Rumple Hill Lot #10 on Right PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 8% +-	0-24	SAB W C-CL	FR SS S SCxP	Relic Gold & Tan 36" Mottled Relic				
		24-48	V SAB-ABK C SAP Fri	FR SS SP SCxP					
2	R-L 7% 10+-	0-8	SAB SCL	FR					
		8-20	SAB C	FR SS SCxP					
		20-50	SAB C/SAP mica	FR VFR					
		50+	SAP						
3	H 8-10%	0-6	SAB CL	FR					
		6-24	SAB C	FR SS SP SCxP					
		24-36	SAB C	FR SS SP SCxP	Tan & gold Right Rd				
		36"	WET Soil / WATER						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___