ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson / Heritage Bld APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/6/98

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Lippard Spgs 4 Lot #100 PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	LS 6%	0-16"	Brn SCL GR	FR					PS .3 to 34"
		16"-20"	Rd/Brn C/CL	m-wSBK SS,SP SE,FI					
		20-34"	Rd/Brn CL	wSBK SS,SP SE, FR w/few to many SAP inclus					
		34"-48"	Yel/Brn CL-SL	SAP & weathered Rock & common mica flakes					
2	LS 6%	0-6"	Brn SCL GR	FR					PS .275-.3 to 35"
		6"-24"	Rd/Brn C/CL	m-wSBK S,P,SE,FI					
		24-35"	Rd/Brn to Yel/Brn CL	wSBK SS,SP,SE,FR w/some Rock frags					
		35-48"	CL / Weathered Rock	Mix					
3	LS 6%	0-16"	Brn SCL GR	FR					PS .3 to 48"
		16"-48"	Rd/Brn-Yel/Brn C/CL	SBK SS,SP,SE,FI-FR w/Inclus of SAP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____