DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson / Heritage Bldrs APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/6/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lippard Spgs 4 Lot #99 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L 5-10	0-7"	Brn SCL GR FR						PS
		7-26	Rd/Brn C/CL	m-w SBK SS, SP, SE, FI					.3+ to 45"
		26-45"	Rd/Brn CL	w SBK SS, SP, SE, FR w/ few to common Mica Flakes			many SAP nodules		
		45-48"	Yel/Brn SAP mix w/ Rd/Brn CL & weathered Rock				Rock Common Mica flakes		
2		0-3"	Brn GR SCL FR						PS .3+ to 34" Mica
		3-23"	Rd/Brn C/CL	m-w SBK SS, SP, SE, FI-FR					
		23-34"	Rd/Brn CL	w SBK SS, SP, SE, FR w/ Inclus of SAP & weathered Rock Mix					
		34-48"	Rd/Brn CL/SAP & Wea						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____