DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson / Heritage Blds APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/2/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lippard Spgs 4 Lot #82 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1	L 2-4%	0-4"	Brn SCL GR	FR					PS .3+ to 36"
		4"-36"	Rd/Brn C/CL	m-w SBK SS SP SE FR					
			Some Incus of SAP						
		36-48"	Rd/Brn-Yel/Brn SAP to		Weathered Rock				
2	L 3-4%	0-5"	Brn SCL GR	FR					PS .3 to 38" SAP Incus
		5-26"	Rd/Brn C/CL	m SBK SS SP SE FR					
		26"-38"	Rd/Brn C/CL	m SBK SS SP SE FR w/ few to many Yel/Brn SL					
		38-48"	Rd/Brn CL & Yel-Brn SL SAP	m-w SBK SS SP SE FR					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____