DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson / Heritage Blds APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/5/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #97 Lippard Spgs 4 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1		0-6"	Brn SCL GR	FR					
		6"-28"	Rd/Brn C/CL	mSBK S-SS, SP, SE, F					
		28-31"	Rd/Brn Cl	wSBK SS, SP, SE, FR					
		31"	Hit Rock Could not Auger thru						
2	L 0-10	0-6"	Brn SCL GR	FR					PS
		6-24"	Rd/Brn C/CL	mSBK SS, SP, SE, F-FR					
		24-41"	Rd/Brn Cl	wSBK SS, SP, SE, FR w/ Few to many SAP inclus.					.3
		41"-48"	Rd/Brn Cl & Yel/Brn SL	SAP mix					
3	L NP 0-10	0-3"	Brn SCL GR	FR					PS
		3-12"	Rd/Brn C/CL	mSBK SS, SP, SE, F					.3 to
		12"-34"	Rd/Brn Cl	wSBK SS, SP, SE, FR w/ Few to many SAP inclus. Weathered Rock Fragments & Common Mica Flakes					34"
		34-42"	Rd/Brn C/CL/SAP & Weathered Rock						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____