DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson / Heritage Bldrs APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/2/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lippard Springs 4 Lot #84 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PEDON #	1940 LAND SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 5%10	0-5"	Brn SCL GR	FR					PS .3 to 38"
		5"-30"	Rd/Brn C/Cl	M-w SBK SS, SP SE, F-FR					
		30" Thin Quartz Layer							
		30-38"	Rd/Brn Cl	w SBK SS, SP SE	FR w/Inclus of SAP				
		38-48"	Red/Brn SL	SAP					
2	L P10	0-3"	Brn SCL GR	FR					PS .3
		3"-31"	Rd/Brn C/Cl	m-w SBK SS, SP SE, F-FR w/Inclus of SAP					
		31"-48"	Rd/Brn Cl w/ Interlay	Kaolinite SL SAP & some Weathered Rock Inclus					
3	L 7%	0-10"	Brn SCL GR	FR					PS .3
		10"-30"	Rd/Brn C/Cl	m SBK SS, SP SE, F-FR					
		30-40	Rd/Brn Cl	w SBK SS, SP SE, FR w/ Some Mica					
		Flakes & SAP Inclus							
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____