DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson/Heritage Bldrs APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/3/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lippard Spgs 4 Lot # 85 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND FEATURE/ POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	4% to 6%	0-16	Brn SiL GR FR						PS .3 to 40" SAP Inclus
		6-25"	Rd/Brn C/CL	m-w SBK SS-S SP-SE, FI FR w/few to many					
		25-40"	Rd/Brn CL	w SBK SS-S SP-SE, FI FR w/few to many				Yel/Brn	
		40-48"	Rd/Brn CL & Yel/Brn SAP	mix					
2	4-5%	0-7"	Brn SiL GR FR						PS .3 to 42"
		7-20"	Rd/Brn C/CL	m-w SBK SS-S SP-SE, FI					
		20-42"	Rd/Brn CL	w SBK SS-S SP-SE, FI FR w/few to many					
		SAP	inclus & weathered Rock						
		45-48"	SAP & weathered Rock						
3	6% to 7%	0-6"	Brn SiL GR FR						PS .3
		6-24"	Rd/Brn C/CL	m-w FR SBK SS-S SP-SE, FI FR w/few to many					
		24-48"	Rd/Brn CL	SBK SS, SP-SE, FI FR w/few to many					
				SAP inclus					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____