DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Rick Dyson / Heritage Bldrs APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/5/98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #94 Lippard Spgs PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1	8/10	0-3"	Brw GR SL FR						PS
		3"-28"	Rd/Brw C/CL	mSBK S-SS,SP,SE,FI					
		28"-42"	Rd/Brw CL	wSBK SS,SP,SE,FR	w/SAP/Weathered Rock				.3 to
		Incl 2% Common Mica Flakes							
		42-48"	CL/SAP/Weathered Rock Mix w/common Mica Flakes						42"
2	15/10	0-3"	Brw GR SL FR						PS
		3-24"	Rd/Brw C	mSBK S-SS,SP,SE,FI			few manganese		
		24"-48"	Rd/Brw-Brw CL	wSBK SS,SP,SE,FR w/SAP & weathered					.3
		Rock inclusions & Common Mica Flakes							
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____