I-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mtn Creek Inn / Sean Blair APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-10-09

PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360gpd PROPERTY SIZE: _____

LOCATION OF SITE: Lot 39 Ph 2 Deerfield Woods PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-7	gr VFSL/SCL	friss SP					.3
	7-27	SBK RC	fr SP SSP					
	27-42	wk SBK-massive RCL/SCL	friss SP	common mica SP				
	42-66+	massive LFSL SSP	friss P					
	0-7	gr SBK SCL/SCL	friss SP					.225-.25
	7-40	wk SBK RCL	fr SSP SSP	common gravels in Bo				
	40-58	massive LSSP	friss P					
	0-3	gr SBK/SCL	friss SP					.25-.3
	3-17	wk SBK RC	fr SSP SSP					
	17-36	wk SBK RCL	friss SP	common SSP				
	36-56	massive LFSL SSP	friss P					
	0-17	gr SBK SL/SCL	friss SP					.25-.3
	17-62	wk SBK RCL	friss SP SSP	common SSP				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Gravity 25% Red	Gravity 25% Red
LTAR	.25	.25

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: DR Hanson

OTHER(S) PRESENT: _____