DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mallard Inn — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 6-10-04
PROPOSED FACILITY: SFR — PROPOSED DESIGN FLOW (.1949): 360gpd — PROPERTY SIZE: _____
LOCATION OF SITE: Lot 36 pl 2 Haddon Woods — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	gr brsl sl/scl	frssso					.25
		6-39	wk fsbk rc/pl	fi sp sosp	fair mi sap >30"				.03
		39-53	wk fsbk-massive	C sap fi sso					
2	6%	0-6	wk sbk/gr brsl/scl	frssso					.3
		6-13	wk sbk rc	fi fr sd sosp					
		13-36	wk sbk yr cl	frssso	common mi sap 36"				
3		0-16	gr brsl/scl	frssso					.25-.3
		16-27	wk sbk rc	fi-fr sssp sexp					
		27-51	wk fsbk yr cl	fi fr sss sp /	common mi sap				
4	11%	0-14	gr brsl sl/scl	frssso					.25-.3
		14-53	wk sbk R-yr cl	fi-fr sp sss p sexp	fair mi sap >36"				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Pump/Shallow	Conv/BLS
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [signature]
OTHER(S) PRESENT: _____