DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET____ OF____

PROPERTY I.D.#:_____
DATE:_____
COUNTY:_____

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: Cathy Goodwin OWNER__AGENT:__PHONE:_____
ADDRESS:_____ APPLICATION DATE:_____ DATE EVALUATED_____
PROPOSED FACILITY:_____
PROPERTY SIZE:_____
LOCATION OF SITE: Spring meadows 2nd lot left from ottawa rd
WATER SUPPLY: On-site Well____ Comm. Well___ Public___ Other_____ EVAL. METHOD: Auger Boring___ Pit___ Cut___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1		0to4	L	GR				.1942 Wetness Cond. - yes
	V	4to48	mix of Fill +					.1943 Depth/.1956 Sapr. - NO
	Yes		2:1	clay		10YR	<chroma 2	.1944 Restrictive Hori. - yes
	7 10% 12							.1948 Profile Class. - unsuitable
								Profile LTAR - <.1
2		0to4	L	GR				.1942 Wetness Cond. - yes
	head	4to24	C	Angular	mixed	10YR		.1943 Depth/.1956 Sapr. - NO
		24to48	Clay, Clay	Fill, 2:1	Clay	mottling		.1944 Restrictive Hori. - yes
	slope							.1948 Profile Class. unsuitable
								Profile LTAR - <.1
3		0to4	L	GR				.1942 Wetness Cond. - N/A
	linear	4to18	C	SBK	1:1			.1943 Depth/.1956 Sapr. - N/A
		18to36	CL	weak SBK	1:1			.1944 Restrictive Hori. - N/A
	6%	36to48	B/C					.1948 Profile Class. - PS
								Profile LTAR - .3
4		0to4	L	GR strong				.1942 Wetness Cond. - N/A
	linear	4to24	C	SBK	1:1			.1943 Depth/.1956 Sapr. - N/A
		24to48	CL	medium SBK	1:1			.1944 Restrictive Hori. - N/A
	6%							.1948 Profile Class. - PS
								Profile LTAR - .3

AVAILABLE SPACE (.1945) yes OTHER FACTORS (.1946)_____ SITECLASSIFICATION (.1948) RS on Front of lot
SYSTEM TYPE Pump To @ Conv. lines LONG-TERM ACCEPTANCE RATE(S) .3
EVALUATED BY: J.C. moore OTHER(S) PRESENT: Cathy Goodwin
COMMENTS:_____

000369