13272.

41285

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR JERRY LYNDON DATE 3-4-92. PERMIT NO. 8K-9-A-17-86.

PHONE: Business _____ Home _____

LOCATION Old Mtn. Rd. north of Kyles Xing - go one mile & T.R. into dev. - T.R. on 1st street - go nearly to cul-de-sac on left. S.R. No. _____

SUBDIVISION NAME SPRING MEADOWS DEV. LOT NO. _____ SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 3.5

Garbage Disposal Unit Yes ☑ No ☐

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 18+ acres.

Soil Characteristics Prop. Suitable.


Application Rate 4 gal/sq. ft.

Topography 2-6%

Depth to Water Table 10'+

Rock or other impervious formations none observed.

☑ Basement with Plumbing _____ Basement without Plumbing _____ No Basement _____ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900+ Linear Ft. 300+

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by Wes Sutton

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY Steve Brown

COMMENTS Riser installed on inlet compartment of tank.

CERTIFICATE OF COMPLETION BY Steve Brown DATE 3-4-92.

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold