DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

①

PROPERTY I.D.#: _____
DATE: _____
COUNTY _____

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT Danny Lippard
ADDRESS _____
OWNER _____ AGENT _____ PHONE: _____
APPLICATION DATE: _____ DATE EVALUATED 8-30-94
PROPOSED FACILITY: _____
PROPERTY SIZE: _____

LOCATION OF SITE: Lot #55 Glen Ridge S/D
WATER SUPPLY: On-site Well ____ Comm. Well ____ Public ____ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ____ Cut ____

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (1)(1): TEXTURE	.1941 (1)(2): STRUCTURE	.1941 (1)(3): MINERALOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	4-6%	0-6"	cl	wSBK				.1942 Wetness Cond. - 5
	L	6"-37"	c	mAbk				.1943 Depth/.1956 Sapr. - 40" PS
		37"-40"	C/sap.	Abk/m				.1944 Restrictive Hori. - NA
		40"-48"	Sap/Weathered Rock					.1948 Profile Class. - P4
								Profile LTAR - .3
2	4-6%	0-5"	cl	wSBK				.1942 Wetness Cond. - 5
	L	5"-29"	c	Abk				.1943 Depth/.1956 Sapr. - 32" U
		29"-32"	C/sap.	Abk/m				.1944 Restrictive Hori. -
		32"-48"	Sap.	m				.1948 Profile Class. - U
								Profile LTAR -
3	4-6%	0-6"	cl	wSBK				.1942 Wetness Cond. - 5
	L	6"-27"	c	Abk				.1943 Depth/.1956 Sapr. - 31" U
		27"-31"	C/sap.	Abk/m				.1944 Restrictive Hori. -
		31"-48"	Sap/Weathered Rock					.1948 Profile Class. - U
								Profile LTAR -
4	4-6%	0-7"	cl	wSBK				.1942 Wetness Cond. - 5
	L	7"-30"	c	Abk				.1943 Depth/.1956 Sapr. - 30" U
		30"-48"	Sap/Weathered Rock					.1944 Restrictive Hori. -
								.1948 Profile Class. - U
								Profile LTAR -

AVAILABLE SPACE (.1945) _____ OTHER FACTORS (.1946) _____ SITE CLASSIFICATION (.1948) U

SYSTEM TYPE _____ LONG-TERM ACCEPTANCE RATE(S) _____

EVALUATED BY Michael Dennis OTHER(S) PRESENT Danny Lippard

COMMENTS Request Backhoe

0004641