SHEET____OF____

DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

PROPERTY I.D.#:
DATE:
COUNTY: Iredell

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: Chris Davidson
OWNER___AGENT___PHONE:
ADDRESS:
APPLICATION DATE:___DATE EVALUATED 6-22-94
PROPOSED FACILITY: 4 bedroom
PROPERTY SIZE: 155 X 220 115' back

LOCATION OF SITE: Lot #6 Glenn Ridge
WATER SUPPLY: On-site Well X Comm. Well___Public___Other___EVAL. METHOD: Auger Boring___Pit X Cut___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	(a)(2) STRUCTURE	(a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	LS	0-12/21"	l to cl	sbk	Fi			.1942 Wetness Cond. - N/A
	12%	>12/21"	rock					.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. - 21" to Rock
								.1948 Profile Class. - U
								Profile LTAR -
2	LS	0-9"	L	GR	FR			.1942 Wetness Cond. - N/A
	12%	9"to24"	C	ABK	Fi			.1943 Depth/.1956 Sapr. - Rock 24"
		24"+	Rock					.1944 Restrictive Hori. - Rock
								.1948 Profile Class. - PS to
		1/2 Pit Face is Rock						Profile LTAR - .125
3	LS	0to17"	L	GR	FR			.1942 Wetness Cond. - N/A
	12to14%	17to30	C	ABK	Fi			.1943 Depth/.1956 Sapr. -
		30to39	Transition		B/C			.1944 Restrictive Hori. - N/A
		[illegible]						.1948 Profile Class. - PS
								Profile LTAR - .4
4	LS	0to13	L	GR	FR			.1942 Wetness Cond. - N/A
	[illegible]	13to30	C	ABK	Fi			.1943 Depth/.1956 Sapr. - 30"
	14%	30to40	weathered Rock Saprolite					.1944 Restrictive Hori. - Rock
								.1948 Profile Class. - U 30
			Pockets of Saprolite In clay Horizon					Profile LTAR - .3

AVAILABLE SPACE (.1945)___OTHER FACTORS (.1946)___SITECLASSIFICATION (.1948)___

SYSTEM TYPE___LONG-TERM ACCEPTANCE RATE(S)___

EVALUATED BY:___OTHER(S) PRESENT:___

COMMENTS: