DIVISION OF ENVIRONMENTAL HEALTH:
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mtn Creek Inn APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-2-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 3 Davidson Woods PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION, SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1 (1A)	8% S	0-6	wk sbk brn scl	fr sssp					
		6-29	wk m sbk R-yBC	fr sp sap					.3
		29-46 (BC)	wk f sbk/abk yR cl	fi-fr sssp	few - common ind sap				
2 (1K)	2% S/L	0-10	wk sbk brn cl	fr sssp					
		10-30	m f sbk RC	fr so sp					.3
		30-46 (B-C)	wk f sbk/ab yR cl	fi-fr sssp	few - common ind sap				
3 (1A)	5% S/L	0-5	wk sbk brn scl	fr sssp					
		5-27	m f sbk RC	fr sp sap					.3
		27-46	wk f-m abk yR cl	fi-fr sssp	few - common ind sap				
4 (1A)	4% S/L	0-6	brn scl						
		6-41	wk f sbk abs having R-yBC cl/ light	fr sp sap					.25
			very wet - some water bleeding into pit						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: DWK
OTHER(S) PRESENT: Now split into SPE's 17A & 134