DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 4-2-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 1 Jackson Woods PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1 14A	4% L	0-5	wk sbk brn scl	fr ss sp					@ 25=.3
		5-17	mt sbk RC	fr ss sp scap					
		17-45 (BC)	wk f-m sbk yr cl	fr ss sp common med sap					
2 14A		0-5	wk sbk brn scl/cl	fr ss sp					.3
		5-24	mt sbk RC	fr ss sp scap					
		24-43 (BC)	wk f-m ABK/sbk yr cl	fr fr ss sp few common med sap					
3 Boller 14A/15A		0-6	wk sbk brn scl	fr ss sp					.3
		6-30	mt sbk RC	fr sp ss sp					
		30-43 (BC)	wk f-m AB yr cl	fr fr sp ss sp few common med sap					
4 15A	4% L 4-15-03	0-8	gr brn scl	fr ss sp					.25
		8-27	mt sbk RC	fr sp scap					
		27-40	m f-m ank yr cl	fr ss sp common y brn mottles some lateral water seeping on t/ horizon change					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: [signature]
OTHER(S) PRESENT: _____

COMMENTS: Split into septic field and 14A(lot 14) & 15A(Lot 15)