DIVISION OF ENVIRONMENTAL HEALTH:
ON-SITE WASTEWATER SECTION

PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mtn Creek Inn APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 4-2-03
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: Lot 3 Davidson Woods PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1 (17A)	8% S	0-6	wk sbk brn sdl	fr sssp					.3
		6-29	wk, m f sbk R-yRC	fr sp sap					
		29-46 (BC)	wk f sbk/mk yRCl	fi-fr sssp	few. common mid sap				
2 (17B)	3% S/L	0-10	wk sbk brn cl	fr sssp					.3
		10-30	m f sbk RC	fr sp sap					
		30-46 (B-C)	wk f sbk/mk yRCl	fi-fr sssp	few. common mid sap				
3 (17A/15A)	5% S/L	0-5	wk sbk brn sdl	fr sssp					.3
		5-27	wk f sbk RC	fr sp sap					
		27-46	wk f-m sbk yRCl	fi-fr sssp	few. common mid sap				
4 (13A)	4% S/L	0-6	brn sdl						.025
		6-47	wk f sbk many F-R brn	fr/ light sp sap					
			very wet - some water standing in pit						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: DM
OTHER(S) PRESENT:
Now split into SFE's 17A & 13A