IREDELL COUNTY HEALTH DEPARTMENT

STATESVILLE 704-878-5305 MOORESVILLE 704-664-5281

IMPROVEMENT PERMIT / CERTIFICATE OF COMPLETION / OPERATION PERMIT / EXISTING SYSTEM INSPECTION

PROPERTY DESCRIPTION NO. C68478 DATE 8/7/97 TAX MAP NO. 4723723073 Watershed: ☐ Yes ☐ No

OWNER OR CONTRACTOR Frank Davidson PHONE: Business Home 872-6556

ADDRESS 107 Ramblewood Dr. Statesville NC 28677

LOCATION Buffalo Shoals Rd, Rt on Ramblewood, 2nd Lot on LS

SUBDIVISION Ramblewood BLOCK / SECTION LOT 107 LOT AREA SITE CLASS. DESIGN FLOW L.T.A.R.

Septic Tank: 1000 Gallons; STB Date	☐ New System ☑ Repair System Type: I, II, III, IV, V, VI	☐ House/Mod. Home No. Bedrooms 3	Water Supply:
Pump Tank: Gallons; PT Date	System Description: Exist	☑ Mobile Home No. Bathrooms 2	☐ Individual
Pump Make: Model Serial No.	Repair System Description:	☐ Business No. Employees	☐ Community
Nitrification Field: No Fields Square Feet Linear Feet	Maintenance Agreement Required: ☐ Yes ☐ No	☐ Other	☐ Public
No Lines Trench Width Max Trench Bottom Depth Gravel Depth	☐ Slab ☐ Crawl Space ☐ Basement w/plumbing ☐ Basement wo/plumbing		

Comments: Exist

Comments:

INITIAL SITE SKETCH

AS BUILT SKETCH

Exist system appeared by Jack Moore, Maxine Ohio System shows no sign of malfunction at time of inspection.

I understand that this permit can be suspended or revoked if any false information is supplied toward securing the permit/any unauthorized changes are made to the site/any unauthorized changes are made in the installation of the system. Improvement Permit is valid for 60 months from date of issuance.

Signed: Installed by:

Improvement Permit by: date Certificate of Completion by: date

Existing System Inspection by: date 8/7/97 Operation Permit by: date

HEALTH DEPT. COPY: WHITE INSPECTION COPY (FINAL): GREEN OWNER COPY (FINAL): YELLOW INSPECTION COPY (INITIAL): PINK OWNER COPY (INITIAL): GOLD