11358.

IREDELL COUNTY HEALTH DEPARTMENT

36795

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR JERRY ALEXANDER DATE 4-11-90. PERMIT NO. 8K-4-A-40.

PHONE: Business _____ Home _____

LOCATION Enter Ashbrook Park off Hwy 70W - T.R. at forks - 3rd house on left. S. R. No. _____


SUBDIVISION NAME ASHBROOK PARK LOT NO. 40 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Addition of swimming pool.

No. Bedrooms _____ No. Bathrooms _____
Garbage Disposal Unit Yes ( ) No ( )
Auto. Dishwasher Yes ( ) No ( )
Auto. Wash. Machine Yes ( ) No ( )
Site Suitable Yes (✓) No ( )
Lot Area EXISTING.

Character & Porosity of Soil _____
Percolation Rate EXISTING SEPTIC
Topography _____
Depth to Water Table TANK SYSTEM.
Rock or other impervious formations _____

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank EXISTING. Gals.
Nitrification Field:
No. of Lines _____
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing septic tank system functioning properly at the time of inspection.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: Steve Brown DATE 4-11-90.

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold