J. R. Wooten Bldr.

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Mrs Ruby Blackwelder DATE 10-1-75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 64-70 W. Cross 3rd Creek. Go approx 1/2 Mile. House on L.

SUBDIVISION NAME Hickory Hills LOT NO. 2 SECTION OR BLOCK NO. _____ S. R. No. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes ( )	No (✓)
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area 20,000 Sq/ft


Character & Porosity of Soil Yellowish Clay With Gravel

Percolation Rate _____

Topography Slight Slope to East

Depth to Water Table Low

Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public (✓)

Installed by Haba Septic Tank Co.

IMPROVEMENTS PERMIT BY _____

COMMENTS: House Not Stubbed out as original Plans Called for.

CERTIFICATE OF COMPLETION BY E. G. Stutesman DATE 10-1-75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold